VINI.AZ
maşınınızın tarixçəsi

# Vini hesabatı

Tarix: 04/11/2026



ID: SAMPLE-FLOOD

## JM3ER293870126693

| | |
|---|---|
| Marka | Mazda |
| Model | CX-7, Grand Touring |
| İl | 2007 |
| Yürüş | 37,210 km |
| İstehsal ölkə | Japan |

| | |
|---|---|
| Qəzalar | 0 qeyd |
| Auksion / Sığorta qeydləri | 4 qeyd |
| Oğurluq | 0 qeyd |
| Suda batırması | 2 qeyd |
| Odometri | 0 qeyd |
| **Ümumi qiymətləndirilməsi** | **Problem var!** |

## YÜRÜŞ

| Tarix | Yer | Yürüş |
|---|---|---|
| 28/01/2011 | FL | 37,210 km |
| 23/12/2010 | VA | 37,150 km |
| 06/12/2010 | VA | 37,150 km |

## QƏZALAR

Qeydlər tapılmadı ...

## ZƏRƏR QEYDLƏRI

Qeydlər tapılmadı ...

## AUKSION / SIĞORTA QEYDLƏRI

| Tarix | Hərrac / Təşkilat | Yer | Ətraflı |
|---|---|---|---|
| 24/09/2012 | ALLSTATE INSURANCE COMPANY | RICHMOND, VA | Brenderin Kodu: I200004<br>Brendrin Adı: ALLSTATE INSURANCE COMPANY<br>Brenderin Şəhəri: RICHMOND<br>Brenderin ştatı: VA<br>Brenderin Telefonu: 8043465800<br>Tarix: 2012-09-24<br>Qeydin Növü: Insurers |
| 07/02/2011 | COPART INC. | DALLAS, TX | Brenderin Kodu: P000001<br>Brendrin Adı: COPART INC.<br>Brenderin Şəhəri: DALLAS<br>Brenderin ştatı: TX<br>Brenderin Telefonu: 9723915000<br>Tarix: 2011-02-07<br>Qeydin Növü: Junk And Salvage<br>Status: SOLD<br>İxrac Üçün: N |

| Tarix | Hərrac / Təşkilat | Yer | Ətraflı |
|---|---|---|---|
| 15/10/2010 | Copart, Inc. | Fairfield, CA | Brenderin Kodu: P000001<br>Brendrin Adı: Copart, Inc.<br>Brenderin Şəhəri: Fairfield<br>Brenderin ştatı: CA<br>Brenderin Telefonu: 7076395294<br>Tarix: 2010-10-15<br>Qeydin Növü: Junk And Salvage<br>Status: TO BE DETERMINED<br>İxrac Üçün: N |
| 15/10/2010 | Copart, Inc. | Fairfield, CA | Brenderin Kodu: P000001<br>Brendrin Adı: Copart, Inc.<br>Brenderin Şəhəri: Fairfield<br>Brenderin ştatı: CA<br>Brenderin Telefonu: 7076395294<br>Tarix: 2010-10-15<br>Qeydin Növü: Junk And Salvage<br>Status: SOLD<br>İxrac Üçün: N |

## OĞURLUQ

Qeydlər tapılmadı ...

## SATIŞLAR

Qeydlər tapılmadı ...

## ƏLAVƏ YOXLANILMASI

| Yoxlama adı | Ətraflı |
|---|---|
| ⊗ Flood damage | **Qeyd #1**<br>Brenderin Kodu: FL<br>Brendrin Adı: FLORIDA<br>Kod: 01<br>Tarix: 2011-01-26<br>Brenderin Növü: State<br><br>**Qeyd #2**<br>Brenderin Kodu: VA<br>Brendrin Adı: VIRGINIA<br>Kod: 01<br>Tarix: 2010-12-23<br>Brenderin Növü: State |
| ✓ Fire damage | OK |
| ✓ Hail damage | OK |
| ✓ Salt water damage | OK |
| ✓ Vandalism | OK |
| ✓ Kit | OK |
| ✓ Dismantled | OK |

| Yoxlama adı | Ətraflı |
| --- | --- |
| Junk | OK |
| Rebuilt | OK |
| Reconstructed | OK |
| Salvage: Damage or Not Specified | Brenderin Kodu: VA<br>Brendrin Adı: VIRGINIA<br>Kod: 11<br>Tarix: 2010-12-06<br>Brenderin Növü: State |
| Salvage: Stolen | OK |
| Salvage: Reasons Other Than Damage or Stolen | OK |
| Test Vehicle | OK |
| Refurbished | OK |
| Collision | OK |
| Salvage Retention | OK |
| Prior Taxi | OK |
| Prior Police | OK |
| Original Taxi | OK |
| Original Police | OK |
| Remanufactured | OK |
| Gray Market | OK |
| Warranty Return | OK |
| Antique | OK |
| Classic | OK |
| Agricultural Vehicle | OK |
| Logging Vehicle | OK |
| Street Rod | OK |
| Vehicle Contains Reissued VIN | OK |
| Replica | OK |
| Totaled | OK |
| Owner Retained | OK |
| Bond Posted | OK |
| Memorandum Copy | OK |
| Parts Only | OK |
| Recovered Theft | OK |
| Undisclosed Lien | OK |
| Prior Owner Retained | OK |
| Vehicle Non-conformity Uncorrected | OK |
| Vehicle Non-conformity Corrected | OK |
| Vehicle Safety Defect Uncorrected | OK |

| Yoxlama adı | Ətraflı |
| --- | --- |
| Vehicle Safety Defect Corrected | OK |
| VIN Replaced | OK |
| Gray Market: Non-compliant | OK |
| Gray Market: Compliant | OK |
| Manufacturer Buy Back | OK |
| Former Rental | OK |
| Disclosed Damage | OK |
| Prior Non-Repairable / Repaired | OK |
| Crushed | OK |
| Hazardous | OK |
| Odometer: Actual | OK |
| Odometer: Not Actual | OK |
| Odometer: Tampering Verified | OK |
| Odometer: Exempt from Odometer Disclosure | OK |
| Odometer: Exceeds Mechanical Limits | OK |
| Odometer: May be Altered | OK |
| Odometer: Replaced | OK |
| Odometer: Reading at Time of Renewal | OK |
| Odometer: Discrepancy | OK |
| Odometer: Call Title Division | OK |
| Odometer: Exceeds Mechanical Limits Rectified | OK |

VINI.AZ
maşınınızın tarixçəsi

# Xüsusiyyətlər

Tarix: 04/11/2026

## JM3ER293870126693

| | |
|---|---|
| Marka | Mazda |
| Model | CX-7, Grand Touring |
| İl | 2007 |
| İstehsal ölkə | Japan |

## XÜSUSIYYƏTLƏR

| | |
|---|---|
| Tərzi | SUV (4-Door) |
| Növü | SUV |
| Ölçü | Midsize |
| Kateqoriya | Sport Utility Vehicles |
| Qapılar | 4 |
| Yanacaq Növü | Premium Unleaded (Required) |
| Yanacaq Tutumu | 68.89 l |
| Yanacaq sərfiyyəti (Şəhər) | 12.38 l / 100 km |
| Yanacaq Sərfiyyəti (Trasda) | 9.80 l / 100 km |

| | |
|---|---|
| Mühərrik | 2.3L L4 DOHC 16V TURBO |
| Mühərrikin həcmi | 2.3 |
| Mühərrikin Silindrləri | 4 |
| Ötürücü Növü | Automatic |
| Ötürücülərin sayı | 6 |
| Aparıcı Təkərlər | Front Wheel Drive |
| Əyləc Sistemi | 4-Wheel ABS |
| Sükan Növü | R&P |
| Çəki | 1,683 kq |

| | |
|---|---|
| Brutto Çəkisi | 0 kq |
| Ümumi Hündürlüyü | 165 sm |
| Ümumi Uzunluğu | 467 sm |
| Ümumi Eni | 187 sm |
| Oturacaqların sayı | 5 |
| Əlavə Oturacaqlar | |
| Qiyməti | $22,225 |
| Çatdırılma Qiyməti | $595 |
| MSRP | $23,750 |

## AVADANLIQ

### Audio sistemi

| | |
|---|---|
| In Dash Cd | 6 Cd Player |
| Radio | Am/Fm |
| Satellite Radio | Sirius |
| Premium Brand Speakers | Bose |
| Premium Brand Audio System | Bose |
| Speed Sensitive Volume Control | |
| Surround Audio | 5.1 |
| Total Number of Speakers | 9 |
| Mp3 Player | Cd Mp3 Playback |
| Radio Data System | |
| Subwoofer | 1 |
| In Dash Cd | Single Cd Player |
| Total Number of Speakers | 4 |
| Antenna Type | Mast |

### Asma

| | |
|---|---|
| Front Suspension Classification | Independent |
| Rear Spring Type | Coil Springs |
| Independent Suspension | Four-Wheel |
| Rear Suspension Type | Multi-Link |
| Rear Arm Type | Trailing Links, Lateral Links |
| Rear Suspension Classification | Independent |
| Front Arm Type | Lower Control Arms |
| Front Stabilizer Bar | Stabilizer Bar |
| Front Spring Type | Coil Springs |
| Rear Stabilizer Bar | Stabilizer Bar |
| Front Suspension Type | Macpherson Strut |

### Əyləc sistemi

### Təhlükəsizlik

| | |
|---|---|
| Rear Brake Width | 2 sm |
| Front Brake Width | 3 sm |
| Rear Brake Type | Ventilated Disc |
| Electronic Brakeforce Distribution | |
| Front Brake Diameter | 29 sm |
| Front Brake Type | Ventilated Disc |
| Antilock Braking System | 4-Wheel ABS |
| Rear Brake Diameter | 30 sm |

| | |
|---|---|
| Child Safety Locks | |
| Child Seat Anchors | |
| Head Airbags | Front and Rear |
| Passenger Airbag Deactivation | Occupant Sensing Deactivation |
| Side Curtain Airbag Rollover Sensor | Side-Curtain Airbag Rollover Sensor |
| Side Airbags | Dual Front |
| Passenger Airbag | Standard |
| Depowered Airbags | Standard |

## Ölçülər

| | |
|---|---|
| Overall Width Without Mirrors | 187 sm |
| Wheelbase | 275 sm |
| Overall Length | 468 sm |
| Minimum Ground Clearance | 8.1 |
| Overall Height | 165 sm |
| Rear Track | 161 sm |
| Front Track | 162 sm |

## Pəncərələr

| | |
|---|---|
| Remote Window Operation | |
| Privacy Glass | |
| One Touch Windows | 2 |
| Power Windows | |
| Rear Wiper | Intermittent Rear Wiper |
| Rear Defogger | |
| Intermittent Front Wipers | Variable Intermittent |

## Şinlər

| | |
|---|---|
| Rear Tire Width | 597 sm |
| Tire Type | All Season |
| Rear Tire Prefix | P |
| Rear Tire Diameter | 46 sm |
| Rear Tire Profile | 152 sm |
| Rear Tire Speed Rating | H |

## İqlim sistemi

| | |
|---|---|
| Front Air Conditioning Zones | Single |
| Front Air Conditioning | Air Conditioning |
| Rear Heat | Rear Ventilation Ducts |
| Air Filtration | Interior Air Filtration |

## Təkərlər

| | |
|---|---|
| Wheel Locks | Front and Rear |
| Rim Type | Alloy |
| Rear Wheel Diameter | 46 sm |
| Rear Wheel Width | 19 sm |

## Güzgülər

| | |
|---|---|
| 1st Row Vanity Mirrors | Dual Vanity Mirrors |
| Passenger Side Mirror Adjustment | Power |
| Driver Side Mirror Adjustment | Power |

## Təhlükəsizlik sistemi

| | |
|---|---|
| Engine Immobilizer | |
| Power Door Locks | Remote Power Door Locks |
| 2 Stage Unlocking | Remote 2-Stage Unlocking |

## Ehtiyat təkəri

| | |
|---|---|
| Spare Wheel Rim Type | Steel |
| Spare Tire Size | Temporary |
| Spare Tire Mount Location | Inside |

## Sükan

## Sükan idarə edilməsi

| | |
|---|---|
| Steering Wheel Adjustments | Tilt-Adjustable |
| Cruise Controls On Steering Wheel | Cruise Controls |
| Audio Controls On Steering Wheel | Audio Controls |

| | |
|---|---|
| Power Steering | Speed-Proportional Power Steering |