VINI.AZ
maşınınızın tarixçəsi

Vini hesabatı

Tarix: 04/11/2026

ID: SAMPLE-THEFT

19UUA66294A040671

Marka	Acura
Model	TL, 3.2
İl	2004
Yürüş	Problem var!
İstehsal ölkə	United States

Qəzalar	0 qeyd
Auksion / Sığorta qeydləri	0 qeyd
Oğurluq	2 qeyd
Suda batırması	0 qeyd
Odometri	0 qeyd
Ümumi qiymətləndirilməsi	**Problem var!**

YÜRÜŞ

Tarix	Yer	Yürüş
14/04/2016	NY	EXEMPT
24/04/2008	NJ	76,046 km
03/05/2004	NJ	24 km

QƏZALAR

Qeydlər tapılmadı ...

ZƏRƏR QEYDLƏRI

Qeydlər tapılmadı ...

AUKSION / SIĞORTA QEYDLƏRI

Qeydlər tapılmadı ...

OĞURLUQ

Tarix	Yer	Ətraflı
24/11/2018	NJ	ID: 5C004826371 Qeydin Növü: Theft Mənbəyin Adı: National Insurance Crime Bureau Mənbəyin Telefonu: 800-447-6282 Mənbəyin Saytı: www.nicb.org Mənbəyin Yeri: www.nicb.org, IL, 60018
24/11/2018	NJ	ID: 5C004826371 Qeydin Növü: Theft Recovery Mənbəyin Adı: National Insurance Crime Bureau Mənbəyin Telefonu: 800-447-6282 Mənbəyin Saytı: www.nicb.org Mənbəyin Yeri: www.nicb.org, IL, 60018

SATIŞLAR

Qeydlər tapılmadı ...

ƏLAVƏ YOXLANILMASI

Yoxlama adı	Ətraflı
Flood damage	OK
Fire damage	OK
Hail damage	OK
Salt water damage	OK
Vandalism	OK
Kit	OK
Dismantled	OK
Junk	OK
Rebuilt	OK
Reconstructed	OK
Salvage: Damage or Not Specified	OK
Salvage: Stolen	OK
Salvage: Reasons Other Than Damage or Stolen	OK
Test Vehicle	OK
Refurbished	OK
Collision	OK
Salvage Retention	OK
Prior Taxi	OK
Prior Police	OK
Original Taxi	OK
Original Police	OK
Remanufactured	OK
Gray Market	OK
Warranty Return	OK
Antique	OK
Classic	OK
Agricultural Vehicle	OK
Logging Vehicle	OK
Street Rod	OK
Vehicle Contains Reissued VIN	OK
Replica	OK
Totaled	OK

Yoxlama adı	Ətraflı
Owner Retained	OK
Bond Posted	OK
Memorandum Copy	OK
Parts Only	OK
Recovered Theft	OK
Undisclosed Lien	OK
Prior Owner Retained	OK
Vehicle Non-conformity Uncorrected	OK
Vehicle Non-conformity Corrected	OK
Vehicle Safety Defect Uncorrected	OK
Vehicle Safety Defect Corrected	OK
VIN Replaced	OK
Gray Market: Non-compliant	OK
Gray Market: Compliant	OK
Manufacturer Buy Back	OK
Former Rental	OK
Disclosed Damage	OK
Prior Non-Repairable / Repaired	OK
Crushed	OK
Hazardous	OK
Odometer: Actual	OK
Odometer: Not Actual	OK
Odometer: Tampering Verified	OK
Odometer: Exempt from Odometer Disclosure	OK
Odometer: Exceeds Mechanical Limits	OK
Odometer: May be Altered	OK
Odometer: Replaced	OK
Odometer: Reading at Time of Renewal	OK
Odometer: Discrepancy	OK
Odometer: Call Title Division	OK
Odometer: Exceeds Mechanical Limits Rectified	OK

VINI.AZ
maşınınızın tarixçəsi

Xüsusiyyətlər

Tarix: 04/11/2026

19UUA66294A040671

Marka	Acura
Model	TL, 3.2
İl	2004
İstehsal ölkə	United States

XÜSUSIYYƏTLƏR

Tərzi	Sedan (4-Door)
Növü	Car
Ölçü	Midsize
Kateqoriya	Midsize Cars
Qapılar	4
Yanacaq Növü	Premium Unleaded (Required)
Yanacaq Tutumu	64.35 l
Yanacaq sərfiyyəti (Şəhər)	11.76 l / 100 km
Yanacaq Sərfiyyəti (Trasda)	8.40 l / 100 km

Mühərrik	3.2L V6 SOHC 24V
Mühərrikin həcmi	3.2
Mühərrikin Silindrləri	6
Ötürücü Növü	Automatic
Ötürücülərin sayı	5
Aparıcı Təkərlər	Front Wheel Drive
Əyləc Sistemi	4-Wheel ABS
Sükan Növü	R&P
Çəki	1,622 kq

Brutto Çəkisi	0 kq
Ümumi Hündürlüyü	144 sm
Ümumi Uzunluğu	481 sm
Ümumi Eni	183 sm
Oturacaqların sayı	5
Əlavə Oturacaqlar	
Qiyməti	$29,755
Çatdırılma Qiyməti	$570
MSRP	$32,650

AVADANLIQ

Audio sistemi

In Dash Cd	6 Cd Player
Total Number of Speakers	8
Antenna Type	Element
Audio Security System	
Radio	Am/Fm
Satellite Radio	Xm
Watts	225
Cassette	
Subwoofer	1

Əyləc sistemi

Rear Brake Width	1 sm
Front Brake Width	3 sm
Rear Brake Type	Disc
Electronic Brakeforce Distribution	
Front Brake Diameter	29 sm
Front Brake Type	Ventilated Disc
Antilock Braking System	4-Wheel ABS
Braking Assist	
Rear Brake Diameter	28 sm

Güzgülər

Auto Dimming Rearview Mirror	Electrochromatic
1st Row Vanity Mirrors	Dual Illuminated Vanity Mirrors
Side Mirror Memory	Includes Exterior Mirrors
Heated Driver Side Mirror	Heated

Ölçülər

Overall Width Without Mirrors	183 sm
Wheelbase	274 sm
Overall Length	481 sm
Minimum Ground Clearance	5.8
Overall Height	144 sm

Passenger Side Mirror Adjustment	Power
Reverse Tilt Side Mirrors	Dual Mirrors
Driver Side Mirror Adjustment	Power
Heated Passenger Side Mirror	Heated

Rear Track	157 sm
Front Track	158 sm

Təhlükəsizlik

Child Safety Locks	
Child Seat Anchors	
Head Airbags	Front and Rear
Passenger Airbag Deactivation	Occupant Sensing Deactivation
Side Airbags	Dual Front
Passenger Airbag	Standard
Depowered Airbags	Standard

Şinlər

Rear Tire Width	597 sm
Tire Type	All Season
Rear Tire Prefix	P
Rear Tire Diameter	43 sm
Rear Tire Profile	114 sm
Rear Tire Speed Rating	W

Pəncərələr

Remote Window Operation	
Speed Sensitive Front Wipers	Speed Sensitive
One Touch Windows	1
Power Windows	
Rear Defogger	
Intermittent Front Wipers	Variable Intermittent

İqlim sistemi

Climate Control Memory	Includes Climate Control
Front Air Conditioning Zones	Dual
Front Air Conditioning	Automatic Climate Control
Rear Heat	Rear Ventilation Ducts
Air Filtration	Interior Air Filtration

Sükan

Steering Wheel Adjustments	Tilt and Telescopic
Cruise Controls On Steering Wheel	Cruise Controls
Steering Wheel Trim	Leather
Phone Controls On Steering Wheel	
Audio Controls On Steering Wheel	Audio Controls

Baş işıqları

Front Fog Lights	Front Fog/Driving Lights
Self Leveling Headlights	Self-Leveling
Headlights Auto Delay	Auto Delay Off
Xenon Headlights	Xenon High Intensity Discharge

Təhlükəsizlik sistemi

Engine Immobilizer	
Power Door Locks	Remote Power Door Locks
Anti Theft Alarm System	Remote Anti-Theft Alarm System
2 Stage Unlocking	Remote 2-Stage Unlocking

Ehtiyat təkəri

Spare Wheel Rim Type	Steel
Spare Tire Size	Temporary
Spare Tire Mount Location	Inside

Asma

Təkərlər

Independent Suspension	Four-Wheel
Rear Suspension Type	Multi-Link
Front Suspension Type	Double Wishbone

Rim Type	Alloy
Rear Wheel Diameter	43 sm
Rear Wheel Width	20 sm

Lyuk

One Touch Power Sunroof	One-Touch Power Sunroof
Sunroof	Power Glass

Sükan idarə edilməsi

Power Steering	Speed-Proportional Power Steering