VINI.AZ
your car history

# Vini report

Date: 04/11/2026



ID: SAMPLE-THEFT

## 19UUA66294A040671

| | |
|---|---|
| Make | Acura |
| Model | TL, 3.2 |
| Year | 2004 |
| Mileage | Problems found! |
| Made In | United States |

| | |
|---|---|
| Accidents | 0 records |
| Auction / Insurance records | 0 records |
| Thefts | 2 records |
| Flood | 0 records |
| Odometer | 0 records |
| **Overall rating** | **Problems found!** |

## MILEAGE

| Date | Location | Mileage |
|---|---|---|
| 14/04/2016 | NY | EXEMPT |
| 24/04/2008 | NJ | 76,046 km |
| 03/05/2004 | NJ | 24 km |

## ACCIDENTS

Records not found...

## SALVAGE RECORDS

Records not found...

## AUCTION / INSURANCE RECORDS

Records not found...

## THEFTS

| Date | Location | Details |
|---|---|---|
| 24/11/2018 | NJ | ID: 5C004826371<br>Record Type: Theft<br>Source Name: National Insurance Crime Bureau<br>Source Phone: 800-447-6282<br>Source Website: www.nicb.org<br>Source Location: www.nicb.org, IL, 60018 |

| Date | Location | Details |
|---|---|---|
| 24/11/2018 | NJ | ID: 5C004826371<br>Record Type: Theft Recovery<br>Source Name: National Insurance Crime Bureau<br>Source Phone: 800-447-6282<br>Source Website: www.nicb.org<br>Source Location: www.nicb.org, IL, 60018 |

## SALES

Records not found...

## ADDITIONAL CHECKS

| Check title | Details |
|---|---|
| Flood damage | OK |
| Fire damage | OK |
| Hail damage | OK |
| Salt water damage | OK |
| Vandalism | OK |
| Kit | OK |
| Dismantled | OK |
| Junk | OK |
| Rebuilt | OK |
| Reconstructed | OK |
| Salvage: Damage or Not Specified | OK |
| Salvage: Stolen | OK |
| Salvage: Reasons Other Than Damage or Stolen | OK |
| Test Vehicle | OK |
| Refurbished | OK |
| Collision | OK |
| Salvage Retention | OK |
| Prior Taxi | OK |
| Prior Police | OK |
| Original Taxi | OK |
| Original Police | OK |
| Remanufactured | OK |
| Gray Market | OK |
| Warranty Return | OK |
| Antique | OK |
| Classic | OK |

| Check title | Details |
| --- | --- |
| Agricultural Vehicle | OK |
| Logging Vehicle | OK |
| Street Rod | OK |
| Vehicle Contains Reissued VIN | OK |
| Replica | OK |
| Totaled | OK |
| Owner Retained | OK |
| Bond Posted | OK |
| Memorandum Copy | OK |
| Parts Only | OK |
| Recovered Theft | OK |
| Undisclosed Lien | OK |
| Prior Owner Retained | OK |
| Vehicle Non-conformity Uncorrected | OK |
| Vehicle Non-conformity Corrected | OK |
| Vehicle Safety Defect Uncorrected | OK |
| Vehicle Safety Defect Corrected | OK |
| VIN Replaced | OK |
| Gray Market: Non-compliant | OK |
| Gray Market: Compliant | OK |
| Manufacturer Buy Back | OK |
| Former Rental | OK |
| Disclosed Damage | OK |
| Prior Non-Repairable / Repaired | OK |
| Crushed | OK |
| Hazardous | OK |
| Odometer: Actual | OK |
| Odometer: Not Actual | OK |
| Odometer: Tampering Verified | OK |
| Odometer: Exempt from Odometer Disclosure | OK |
| Odometer: Exceeds Mechanical Limits | OK |
| Odometer: May be Altered | OK |
| Odometer: Replaced | OK |
| Odometer: Reading at Time of Renewal | OK |
| Odometer: Discrepancy | OK |
| Odometer: Call Title Division | OK |
| Odometer: Exceeds Mechanical Limits Rectified | OK |

VINI.AZ
your car history

# Specifications

Date: 04/11/2026

## 19UUA66294A040671

| | |
|---|---|
| **Make** | Acura |
| **Model** | TL, 3.2 |
| **Year** | 2004 |
| **Made In** | United States |

## SPECIFICATIONS

| | |
|---|---|
| Vehicle Style | Sedan (4-Door) |
| Vehicle Type | Car |
| Vehicle Size | Midsize |
| Vehicle Category | Midsize Cars |
| Doors | 4 |
| Fuel Type | Premium Unleaded (Required) |
| Fuel Capacity | 64.35 l |
| City Mileage | 11.76 l / 100 km |
| Highway Mileage | 8.40 l / 100 km |

| | |
|---|---|
| Engine | 3.2L V6 SOHC 24V |
| Engine Size | 3.2 |
| Engine Cylinders | 6 |
| Transmission Type | Automatic |
| Transmission Gears | 5 |
| Driven Wheels | Front Wheel Drive |
| Anti-Brake System | 4-Wheel ABS |
| Steering Type | R&P |
| Curb Weight | 1,622 kg |

| | |
|---|---|
| Gross Weight | 0 kg |
| Overall Height | 144 cm |
| Overall Length | 481 cm |
| Overall Width | 183 cm |
| Standard Seating | 5 |
| Optional Seating | |
| Invoice Price | $29,755 |
| Delivery Charges | $570 |
| MSRP | $32,650 |

## EQUIPMENT

### Audio system

| | |
|---|---|
| In Dash Cd | 6 Cd Player |
| Total Number of Speakers | 8 |
| Antenna Type | Element |
| Audio Security System | |
| Radio | Am/Fm |
| Satellite Radio | Xm |
| Watts | 225 |
| Cassette | |
| Subwoofer | 1 |

### Brakes system

| | |
|---|---|
| Rear Brake Width | 1 cm |
| Front Brake Width | 3 cm |
| Rear Brake Type | Disc |
| Electronic Brakeforce Distribution | |
| Front Brake Diameter | 29 cm |
| Front Brake Type | Ventilated Disc |
| Antilock Braking System | 4-Wheel ABS |
| Braking Assist | |
| Rear Brake Diameter | 28 cm |

### Mirrors

| | |
|---|---|
| Auto Dimming Rearview Mirror | Electrochromatic |
| 1st Row Vanity Mirrors | Dual Illuminated Vanity Mirrors |
| Side Mirror Memory | Includes Exterior Mirrors |
| Heated Driver Side Mirror | Heated |
| Passenger Side Mirror Adjustment | Power |

### Dimensions

| | |
|---|---|
| Overall Width Without Mirrors | 183 cm |
| Wheelbase | 274 cm |
| Overall Length | 481 cm |
| Minimum Ground Clearance | 5.8 |
| Overall Height | 144 cm |

| | |
|---|---|
| Reverse Tilt Side Mirrors | Dual Mirrors |
| Driver Side Mirror Adjustment | Power |
| Heated Passenger Side Mirror | Heated |

| | |
|---|---|
| Rear Track | 157 cm |
| Front Track | 158 cm |

## Safety

| | |
|---|---|
| Child Safety Locks | |
| Child Seat Anchors | |
| Head Airbags | Front and Rear |
| Passenger Airbag Deactivation | Occupant Sensing Deactivation |
| Side Airbags | Dual Front |
| Passenger Airbag | Standard |
| Depowered Airbags | Standard |

## Tires

| | |
|---|---|
| Rear Tire Width | 597 cm |
| Tire Type | All Season |
| Rear Tire Prefix | P |
| Rear Tire Diameter | 43 cm |
| Rear Tire Profile | 114 cm |
| Rear Tire Speed Rating | W |

## Windows

| | |
|---|---|
| Remote Window Operation | |
| Speed Sensitive Front Wipers | Speed Sensitive |
| One Touch Windows | 1 |
| Power Windows | |
| Rear Defogger | |
| Intermittent Front Wipers | Variable Intermittent |

## Climate

| | |
|---|---|
| Climate Control Memory | Includes Climate Control |
| Front Air Conditioning Zones | Dual |
| Front Air Conditioning | Automatic Climate Control |
| Rear Heat | Rear Ventilation Ducts |
| Air Filtration | Interior Air Filtration |

## Steering wheel

| | |
|---|---|
| Steering Wheel Adjustments | Tilt and Telescopic |
| Cruise Controls On Steering Wheel | Cruise Controls |
| Steering Wheel Trim | Leather |
| Phone Controls On Steering Wheel | |
| Audio Controls On Steering Wheel | Audio Controls |

## Lights

| | |
|---|---|
| Front Fog Lights | Front Fog/Driving Lights |
| Self Leveling Headlights | Self-Leveling |
| Headlights Auto Delay | Auto Delay Off |
| Xenon Headlights | Xenon High Intensity Discharge |

## Security

| | |
|---|---|
| Engine Immobilizer | |
| Power Door Locks | Remote Power Door Locks |
| Anti Theft Alarm System | Remote Anti-Theft Alarm System |
| 2 Stage Unlocking | Remote 2-Stage Unlocking |

## Spare tire wheel

| | |
|---|---|
| Spare Wheel Rim Type | Steel |
| Spare Tire Size | Temporary |
| Spare Tire Mount Location | Inside |

## Suspension

| | |
|---|---|
| Independent Suspension | Four-Wheel |

## Wheels

| | |
|---|---|
| Rim Type | Alloy |

| | |
|---|---|
| Rear Suspension Type | Multi-Link |
| Front Suspension Type | Double Wishbone |

| | |
|---|---|
| Rear Wheel Diameter | 43 cm |
| Rear Wheel Width | 20 cm |

## Sunroof

| | |
|---|---|
| One Touch Power Sunroof | One-Touch Power Sunroof |
| Sunroof | Power Glass |

## Steering

| | |
|---|---|
| Power Steering | Speed-Proportional Power Steering |