VINI.AZ
история вашей машины

Vini отчёт

Дата: 04/11/2026

ID: SAMPLE-THEFT

19UUA66294A040671

Марка	Acura
Модель	TL, 3.2
Год	2004
Пробег	Есть проблемы!
Сделано в	United States

Аварии	**0 записи**
Аукционные / Страховые записи	**0 записи**
Угон	**2 записи**
Утопление	**0 записи**
Одометр	**0 записи**
Общая оценка	**Есть проблемы!**

ПРОБЕГ

Дата	Место	Пробег
14/04/2016	NY	EXEMPT
24/04/2008	NJ	76,046 км
03/05/2004	NJ	24 км

АВАРИИ

Записей не найдено...

ЗАПИСИ О ПОВРЕЖДЕНИЯХ

Записей не найдено...

АУКЦИОННЫЕ / СТРАХОВЫЕ ЗАПИСИ

Записей не найдено...

УГОН

Дата	Место	Детали
24/11/2018	NJ	ID: 5C004826371 Тип Записи: Theft Источник: National Insurance Crime Bureau Телефон Источника: 800-447-6282 Сайт Источника: www.nicb.org Местоположение Источника: www.nicb.org, IL, 60018
24/11/2018	NJ	ID: 5C004826371 Тип Записи: Theft Recovery Источник: National Insurance Crime Bureau Телефон Источника: 800-447-6282 Сайт Источника: www.nicb.org Местоположение Источника: www.nicb.org, IL, 60018

ПРОДАЖИ

Записей не найдено...

ДОПОЛНИТЕЛЬНЫЕ ПРОВЕРКИ

Название проверки	Детали
Flood damage	OK
Fire damage	OK
Hail damage	OK
Salt water damage	OK
Vandalism	OK
Kit	OK
Dismantled	OK
Junk	OK
Rebuilt	OK
Reconstructed	OK
Salvage: Damage or Not Specified	OK
Salvage: Stolen	OK
Salvage: Reasons Other Than Damage or Stolen	OK
Test Vehicle	OK
Refurbished	OK
Collision	OK
Salvage Retention	OK
Prior Taxi	OK
Prior Police	OK
Original Taxi	OK
Original Police	OK
Remanufactured	OK
Gray Market	OK
Warranty Return	OK
Antique	OK
Classic	OK
Agricultural Vehicle	OK
Logging Vehicle	OK
Street Rod	OK
Vehicle Contains Reissued VIN	OK
Replica	OK
Totaled	OK

Название проверки	Детали
Owner Retained	OK
Bond Posted	OK
Memorandum Copy	OK
Parts Only	OK
Recovered Theft	OK
Undisclosed Lien	OK
Prior Owner Retained	OK
Vehicle Non-conformity Uncorrected	OK
Vehicle Non-conformity Corrected	OK
Vehicle Safety Defect Uncorrected	OK
Vehicle Safety Defect Corrected	OK
VIN Replaced	OK
Gray Market: Non-compliant	OK
Gray Market: Compliant	OK
Manufacturer Buy Back	OK
Former Rental	OK
Disclosed Damage	OK
Prior Non-Repairable / Repaired	OK
Crushed	OK
Hazardous	OK
Odometer: Actual	OK
Odometer: Not Actual	OK
Odometer: Tampering Verified	OK
Odometer: Exempt from Odometer Disclosure	OK
Odometer: Exceeds Mechanical Limits	OK
Odometer: May be Altered	OK
Odometer: Replaced	OK
Odometer: Reading at Time of Renewal	OK
Odometer: Discrepancy	OK
Odometer: Call Title Division	OK
Odometer: Exceeds Mechanical Limits Rectified	OK

VINI.AZ
история вашей машины

Комплектация

Дата: 04/11/2026

19UUA66294A040671

Марка	Acura
Модель	TL, 3.2
Год	2004
Сделано в	United States

КОМПЛЕКТАЦИЯ

Стиль	Sedan (4-Door)
Тип	Car
Размер	Midsize
Категория	Midsize Cars
Двери	4
Тип Топлива	Premium Unleaded (Required)
Ёмкость Бака	64.35 л
Расход топлива (Город)	11.76 л / 100 км
Расход топлива (Трасса)	8.40 л / 100 км

Двигатель	3.2L V6 SOHC 24V
Объём Двигателя	3.2
Двигатель - Цилиндры	6
Коробка Передач	Automatic
Кол-во Передач	5
Ведущие Колеса	Front Wheel Drive
Тормозная Система	4-Wheel ABS
Рулевое Управление	R&P
Снаряженная Масса	1,622 кг

Вес Брутто	0 кг
Общая Высота	144 см
Общая Длина	481 см
Общая Ширина	183 см
Кол-во Сидений	5
Доп. Сиденья	
Стоимость	$29,755
Стоимость Доставки	$570
MSRP	$32,650

КОМПЛЕКТАЦИЯ

Аудио система

In Dash Cd	6 Cd Player
Total Number of Speakers	8
Antenna Type	Element
Audio Security System	
Radio	Am/Fm
Satellite Radio	Xm
Watts	225
Cassette	
Subwoofer	1

Тормозная система

Rear Brake Width	1 см
Front Brake Width	3 см
Rear Brake Type	Disc
Electronic Brakeforce Distribution	
Front Brake Diameter	29 см
Front Brake Type	Ventilated Disc
Antilock Braking System	4-Wheel ABS
Braking Assist	
Rear Brake Diameter	28 см

Зеркала

Auto Dimming Rearview Mirror	Electrochromatic
1st Row Vanity Mirrors	Dual Illuminated Vanity Mirrors
Side Mirror Memory	Includes Exterior Mirrors

Размеры

Overall Width Without Mirrors	183 см
Wheelbase	274 см
Overall Length	481 см

Heated Driver Side Mirror	Heated
Passenger Side Mirror Adjustment	Power
Reverse Tilt Side Mirrors	Dual Mirrors
Driver Side Mirror Adjustment	Power
Heated Passenger Side Mirror	Heated

Minimum Ground Clearance	5.8
Overall Height	144 см
Rear Track	157 см
Front Track	158 см

Безопасность

Child Safety Locks	
Child Seat Anchors	
Head Airbags	Front and Rear
Passenger Airbag Deactivation	Occupant Sensing Deactivation
Side Airbags	Dual Front
Passenger Airbag	Standard
Depowered Airbags	Standard

Шины

Rear Tire Width	597 см
Tire Type	All Season
Rear Tire Prefix	P
Rear Tire Diameter	43 см
Rear Tire Profile	114 см
Rear Tire Speed Rating	W

Окна

Remote Window Operation	
Speed Sensitive Front Wipers	Speed Sensitive
One Touch Windows	1
Power Windows	
Rear Defogger	
Intermittent Front Wipers	Variable Intermittent

Климат контроль

Climate Control Memory	Includes Climate Control
Front Air Conditioning Zones	Dual
Front Air Conditioning	Automatic Climate Control
Rear Heat	Rear Ventilation Ducts
Air Filtration	Interior Air Filtration

Рулевое колесо

Steering Wheel Adjustments	Tilt and Telescopic
Cruise Controls On Steering Wheel	Cruise Controls
Steering Wheel Trim	Leather
Phone Controls On Steering Wheel	
Audio Controls On Steering Wheel	Audio Controls

Головной свет

Front Fog Lights	Front Fog/Driving Lights
Self Leveling Headlights	Self-Leveling
Headlights Auto Delay	Auto Delay Off
Xenon Headlights	Xenon High Intensity Discharge

Система Безопасности

Engine Immobilizer	
Power Door Locks	Remote Power Door Locks
Anti Theft Alarm System	Remote Anti-Theft Alarm System
2 Stage Unlocking	Remote 2-Stage Unlocking

Запасные колёса

Spare Wheel Rim Type	Steel
Spare Tire Size	Temporary
Spare Tire Mount Location	Inside

Подвеска

Колеса

Подвеска

Independent Suspension	Four-Wheel
Rear Suspension Type	Multi-Link
Front Suspension Type	Double Wishbone

Колеса

Rim Type	Alloy
Rear Wheel Diameter	43 см
Rear Wheel Width	20 см

Люк

One Touch Power Sunroof	One-Touch Power Sunroof
Sunroof	Power Glass

Рулевое управление

Power Steering	Speed-Proportional Power Steering